

# **User's Manual**



# **Negger**

## **Contents**

1 Introduction	-
	4
1.1 General Symbols on the instrument	4 4
1.2 Service and support	4
Contact Information	4
Checklist before calling/e-mailing for support	4
Shipping	4
1.3 The calibration kit includes	5
2 The BVM CAL kit	
	6
2.1 BVM CAL Box	6
Battery power	6
Inserting batteries	6
2.2 Other parts in the kit	7
BMV CAL Ref	7
AC Adapter	7
Power & Signal Connector	7
USB Memory stick	7
Cables	7
2.3 Other equipment needed	7
Digital Multimeter (DMM)	7
Computer	7
3 Operation	
	8
3.1 Installing SW	8
3.2 Connect and setup	8
How to set COM port for the digital multim- eter (DMM) (Agilent 34401A) or other equiva-	Q
How to set IP address for the digital multime- ter (DMM) (Agilent 34410A or Keysight 34461	1A 9
3.3 Calibration	10
3.4 Error messages	11
Bad connection	11
Battery failure	11
3.5 System calibration	12
4 Specifications	
	. 14

#### Megger.

# **BVM Cal kit**

#### **Calibration system for BVM units**

# User's Manual

NOTICE OF COPYRIGHT & PROPRIETARY RIGHTS

© 2016-2019, Megger Sweden AB. All rights reserved.

The contents of this manual are the property of Megger Sweden AB. No part of this work may be reproduced or transmitted in any form or by any means, except as permitted in written license agreement with Megger Sweden AB. Megger Sweden AB has made every reasonable attempt to ensure the completeness and accuracy of this document. However, the information contained in this manual is subject to change without notice, and does not represent a commitment on the part of Megger Sweden AB. Any attached hardware schematics and technical descriptions, or software listings that disclose source code, are for informational purposes only. Reproduction in whole or in part to create working hardware or software for other than Megger Sweden AB products is strictly prohibited, except as permitted by written license agreement with Megger Sweden AB.

This device contains software that is licensed under the General Public License (GPL). If requested, a copy of the source code licensed under the GPL can be sent to you. Please e-mail your request to se-gplrequest@megger.com. Please note that no questions regarding the content of the source code can be answered. You may be charged a fee covering the costs of sending you the source code.

#### TRADEMARK NOTICES

Megger® and Programma® are trademarks registered in the U.S. and other countries. All other brand and product names mentioned in this document are trademarks or registered trademarks of their respective companies.

Megger Sweden AB is certified according to ISO 9001 and 14001.

Postal address: Megger Sweden AB

Box 724

Visiting address: Megger Sweden AB Rinkebyvägen 19

SWEDEN

SE-182 36 DANDERYD

SWEDEN **T** +46 8 510 195 00 E seinfo@megger.com

SE-182 17 DANDERYD

www.megger.com

CJ0125BE

# Introduction

#### 1.1 General

This manual is valid for the BVM Cal Box kit and it is designed for use for calibration of the Megger BVM instruments.

#### Symbols on the instrument

SROHS <sup>√</sup>	Rohs means restriction of hazard- ous substances. This is a method of addressing health and environmental concerns that are posed by materials and elements used in electronic equip- ments.
	WEEE, Waste Electrical and Electronic Equipment. Please utilize your lo- cal WEEE collection facilities in the disposal of this product and otherwise

CE

Equipment complies with current EU directives.

observe all applicable requirements.

#### Important

- 1. **Water and moisture.** Do not use the instrument near water. To prevent fire or shock hazard, do not expose the instrument to rain or moisture.
- 2. **Service.** Do not attempt to service the instrument yourself. If you attempt to service the instrument yourself the warranty is no longer valid.
- 3. Accessories. Do not use any accessories that are not intended for use together with the instrument.
- 4. **Cleaning.** Use a damp cloth for cleaning. Do not use liquid cleaners or aerosol cleaners.
- 5. **Servicing**. Refer all servicing to Megger authorized personnel.

#### **1.2 Service and support**

For technical assistance please contact your local Megger representative or direct your request to the office in Sweden.

#### **Contact Information**

Internet:	www.megger.com
E-mail:	support-sweden@megger.com
Tel:	+46 8 510 195 00

# Checklist before calling/e-mailing for support

- Read the manual
- Try to repeat the operation if possible
- Identify the instrument model, serial number and revision of software.

#### Shipping

If you are going to send the instrument with parcel service use the original transport box or one with equivalent strength. Megger can not take responsibility for transport damages.

# 1.3 The calibration kit includes

Qnty	ltem	Part No.
1	BVM CAL Box	CJ-90077
1	BVM CAL Reference	MA-00272
1	Power and signal connector	MA-00271
1	AC adapter	HC-04220
	100-240 V AC to 24 V DC	
1	USB Memory stick	HF-10020
	BVM calib sw Agilent (CJ-8100X)	
	BVM calib sw Keysight (CJ-8110X)	
5	Control cable, black, RJ45, 0.5 m	GA-01100
2	Extension cable, black, 0.5 m	04-30050
2	Test cable, red, 0.5 m	04-35012
1	Test cable, black, 0.5 m	04-35010
1	User's manual	CJ0125XE
1	Transport case	GD-00620

# The BVM CAL kit

#### 2.1 BVM CAL Box



1	Input from Power and Signal Connector (To 1st BVM unit) (RJ45 cable, Order No. GA-01100)
2	Output to BVM unit (IN) unit for calibration (RJ45 cable, Order No. GA-01100)
3	Current measuring output to multimeter Agilent 34401A or 34410A or Keysight 34461A
4	Output to BVM unit for calibration
5	Common output to multimeter
6	Output to BVM CAL Ref unit
7	Voltage measuring output to multimeter

#### **Battery power**

The BVM CAL Box is battery powered (non rechargeable)and function as a voltage reference. The batteries are located under the bottom cover. There are six AAA batteries and one 9V battery.

Recomended battery types		
1.5 V AAA	IEC LR03/ANSI 24D/ANSI 24A	
9 V	IEC 6LR61/ANSI 1604A or IEC 6F22/ANSI 1604D	

#### **Inserting batteries**

**1]** Remove the lid at back by grabbing it and pull backwards.



2] Insert the batteries, observe polarity.



**3**] Replace the lid by pushing it into place until the snap locks will hold it.

#### 2.2 Other parts in the kit

#### **BMV CAL Ref**



#### **AC Adapter**

Power supply, 24 V, for the calibration system. Connects to mains and output to Power and Signal Connector.



#### **Power & Signal Connector**



#### **USB Memory stick**

The USB stick contains the BVM calibration software and the User's manual.

#### Cables

See section 1.3.

# 2.3 Other equipment needed

#### **Digital Multimeter (DMM)**

The system is designed for use together with Agilent 34401A (connected via serial / COM-port) or Agilent 34410A (LAN / Ethernet connected). The system can also be used with Keysight 34461A (LAN / Ethernet connected). Probably also Keysight 34465A, but this has not been tested.

#### Computer

PC with USB port and COM port or Ethernet port, depending on type of DMM (see above).

Cable for connection between PC and DMM, depending on type of instrument (serial null modem cable or Ethernet cable).

**Note:** If the PC is of an older model, and LAN / Ethernet connected DMM is used, a crossover Ethernet cable may be required.



## 3.1 Installing SW

The software is installed from the USB drive. There are two folders in the USB drive. Choose folder according to the DMM that you have.

- A] If you have a DMM type 34401A or 34410A, open folder OLD\_(Agilent).
- **B]** If you have a DMM type 34461A, open folder NEW\_(Keysight).
- **1]** Open folder BVM CAL SW, then double-click setup.exe to install the software.

#### 3.2 Connect and setup

Make connections as shown in the diagram in figure 3.2.1. Supported multimeters are: Agilent 34401A serial connected or Agilent 34410A network connected.

For use with Keysight 34461A, see figure 3.2.2

**Note** A null modem cable is needed for connection of the Digital Multimeter.

#### How to set COM port for the digital multimeter (DMM) (Agilent 34401A) or other equivalent instrument

This step is optional.

1] Enter the COM port number.



Figure 3.2.1 Connection diagram for calibration of BVM units using instrument with COM port

- 2] If you don't enter a COM port number, the software will search the PC for the COM port that the DMM is connected to.
- **3** If the automatic search for right com port does not work you can set it manually.
- **4]** In MS Windows, open the "Control Panel".
- 5] Select "Device Manager".
- 6] Right-click on the port you want and select "Properties", "Port Settings", "Advanced", Select the number on the COM-port (from 1-15).
- **Note** The BVM Cal System can only handle COMports from 1 to 15.

#### How to set IP address for the digital multimeter (DMM) (Agilent 34410A or Keysight 34461A

This step is optional, but recommended.

- 1] Enter DMM IP address in BVM calib.
- **2]** If you don't enter an IP address, the software will search for a connected DMM. Which will take some time.

- **3**] If the automatic search for right IP address does not work you can set it manually.
- 4] It can be found by either starting PC Command window, then typing command "ipconfig", or by entering the menu on the DMM (press buttons Shift, then Display (Utility), then find LAN settings, or refer to DMM User's manual).

The IP address is a series of digits separated by dots. It is normally 169.254.aa.bb, where aa and bb are numbers between 0 and 255.

- **Note** It takes up to one minute to establish connection between PC and DMM.
- **5]** Please refer to the manual for the DMM to find out how to get the IP-address for the instrument.



Figure 3.2.2 Connection diagram for calibration of BVM units using instrument with Ethernet port

## 3.3 Calibration

- **1]** Start the BVMcalib SW as administrator.
- 2] Press "New Unit".
- **3**] Select connection type by clicking ComPort or Ethernet.
- **Note** If the port for the Digital Multimeter (DMM) is not found you shall follow the steps 3 to 5 below.

BVMcalib 2.5.6			J ×
3 Ext. resistor 7 FW version 7	New Unit	DMM ComPort 1 C Ethernet C CMDfiles	
Besistor value			
	5V Range	20V Range	
Old Offse	et [		
Old scale Facto	r 🚺		
New Offse	et [		
New Scale Facto	a 🚺		
Volt ir	י 🔽		
Volt before	• 📃		
Volt afte	a 🚺	Relay test	
Error Afte	a 🚺	Relay ON Relay OFF	
Cal date	3	I I	
		Reject	

The calibration will proceed and data are presented subsequently.

When calibration is ready and if it is approved it is automatically accepted and the new data are saved. Logfiles are saved in C:/ProgramFiles(x86)/BVMcalib.





**5]** Click "Yes". The calibration will start.

BVMcalib 2.5.6			
Calibration done, waiting for next unit			
3	New Unit	DMM	
Ext. resistor	-265	C Ethernet	
FW version	VER R02A	C CMDfiles	
Serial number	21389176		
Resistor value	-373	399.850 -375	
	5V Range	20V Range	
Old Offse	2	1	
Old scale Facto	42821	43156	
New Offse	2		
New Scale Factor	42824	43151	
Volt in	4.8263	19.0617	
Volt before	4.826	19.069	
Volt after	4.826	19.059 Relay test	
Error After	-0.006	-0.014 Relay ON Relay OFF	
Cal date	2013120	13	
		Reject	

## **6]** Disconnect the calibrated BVM unit and connect the next BVM unit.

If the BVM unit does not pass the calibration the faulty value will be highlighted with red, see example below.

BVMcalib 2.5.6		
Connection Both clamps to 0 V		
3	New Unit	DMM © ComPort 1
Ext. resistor	-265	C Ethernet
FW version	VER R02A	C CMDfiles
Serial number	41004	
Resistor value	-610	399.855 -362
	5V Range	20V Range
Old Offs	et 12	2
Old scale Fact	or 42767	43112
New Offs	et 2	0
New Scale Fact	or 42760	43092
Volt	in 4.8262	19.063
Volt befo	re 4.827	19.078
Volt aft	er 4.827	19.060 Relay test
Error Aft	er 0.017	-0.016 Relay ON Relay OFF
Cal da	te 2011090	9
		Reject

7] You can try to run the calibration once again to see if you get the same result. Click "Reject" and then "New Unit" to run a new calibration.

A defective unit should be replaced.

#### 3.4 Error messages

#### **Bad connection**

Here are some examples showing error messages when a connecetion is lost.





**1**] Check all leads and connections.

#### **Battery failure**

If the battery power is to weak you will get the following error message.

BVMcalib 2.5.6		
	Measuring/	/Calculating/Checking
3	New Unit	DMM
Ext. resistor	-265	C Ethernet
FW version	VER R02A	C CMDfiles
Serial number	41004	
Resistor value	-610	
	5V Range	20V Range
Old Offs	et 12	2
Old scale Fact	or 42767	43112
New Offs	et 2	
New Scale Fact	To To	
Volt	in -0.0012	
Volt befo	re	
Volt aft	er 🔽	Relay test
Error Aft	er 🚺	Relay ON Relay OFF
Cal da	te 2011090	19
		Fleient Check voltage source
		Voltage should be between 3 to 5 Volt (is -0.0012)
		ОК

**1]** Check batteries and replace with new batteries.

#### 3.5 System calibration

Every six months the BVM CAL Ref unit should be calibrated. The system can calibrate itself and is done as follows.

- 1] Connect in the same way as for a standard calibration but shift positions for CAL Ref BVM and BVM unit.
- **2]** Run a normal calibration.
- **3**] Shift back to right position for the CAL Ref.

# **S**pecifications

Specifications are valid at fully charged batteries and an ambient temperature of +25°C, (77°F). Specifications are subject to change without notice.

#### **Environment**

Application field	For use in high-voltage substations and industrial environments.
Temperature	
Operation	-20°C to +45°C (-4°F to +113°F) *)
Storage	-40°C to +70°C (-40°F to +158°F)
Relative humidity %RH	5%-95%, non condensing
CE-marking	
EMC	2004/108/EC
LVD	2006/95/EC
RoHS	2011/65/EU
Power supply	
AC adapter	100- 240 V AC to 24 V DC, 50 mA
BVM CAL Box	6(six) 1.5 V AAA batteries and 1 (one) 9 V battery
Safety	Batteries are short circuit protected
Dimensions	
BVM CAL Box	143 X 85 X 80 mm
BVM CAL Reference	75 X 61 X 25 mm
Power and signal con- nector	75 X 61 X 25 mm
AC adapter	115 X 52 X 30 mm
Transport case	270 X 180 X 240 mm
Weight	
BVM Cal Box	0.5 kg
BVM CAL Kit (Incl. transport case)	2.1 kg
Output	
Output voltage	20 V DC (max)

#### Your "One Stop" Source for all your electrical test equipment needs

- Battery Test Equipment
- Cable Fault Locating Equipment
- Circuit Breaker Test Equipment
- Data Communications Test Equipment
- Fiber Optic Test Equipment
- Ground Resistance Test Equipment
- Insulation Power Factor (C&DF) Test Equipment
- Insulation Resistance Test Equipment
- Line Testing Equipment
- Low Resistance Ohmmeters
- Motor & Phase Rotation Test Equipment
- Multimeters
- Oil Test Equipment
- Portable Appliance & Tool Testers
- Power Quality Instruments
- Recloser Test Equipment
- Relay Test Equipment
- T1 Network Test Equipment
- Tachometers & Speed Measuring Instruments
- TDR Test Equipment
- Transformer Test Equipment
- Transmission Impairment Test Equipment
- Watthour Meter Test Equipment
- STATES® Terminal Blocks & Test Switches
- Professional Hands-On Technical and Safety Training Programs

Megger is a leading global manufacturer and supplier of test and measurement instruments used within the electric power, building wiring and telecommunication industries.

With research, engineering and manufacturing facilities in the USA, UK, Germany and Sweden, combined with sales and technical support in most countries, Megger is uniquely placed to meet the needs of its customers worldwide.

Megger is certified according to ISO 9001 and 14001. Megger is a registered trademark.

#### **Megger Group Limited** UNITED KINGDOM Dover, Kent CT17 9EN ENGLAND

- BULGARIA
- CZECH REPUBLIC

- GERMANY
- HUNGARY
- INDONESIA
- KINGDOM OF BAHRAIN
- KOREA
- MALAYSIA
- PAKISTAN
- PHILIPPINES

- POLAND
- ROMANIA
- RUSSIA
- SINGAPORE
- SLOVAK REPUBLIC
- SOUTH AFRICA
- SPAIN
- SWEDEN
- SWITZERLAND
- TAIWAN
- THAILAND
- UNITED ARAB EMIRATES
- USA
- VIETNAM

CE

#### Postal address:

Megger Sweden AB Box 724 SE-182 17 DANDERYD

Visiting address: Megger Sweden AB Rinkebyvägen 19 SE-182 36 DANDERYD



T +46 8 510 195 00 E seinfo@megger.com www.megger.com

SWEDEN

# SWEDEN

- FRANCE

- INDIA