

MFT-X1 Product Advisory

Megger[®]



20-12-2023

If an RCD or touch voltage test is aborted before completion, this may cause an incorrect touch voltage to be displayed. The MFT needs to be reset before you start another test. To do this, perform an RCD or touch voltage test, allowing it to run until completion, or turn the instrument off and back on again. The performance will be improved in a future firmware release.