

MFM10-1 - Sheath Fault Location Unit
Software Release Note
Version 1.590

Products / Variants:

MFM 10-1 (1004818)
MFM 10-1-AF (1004819)
MFM 10 (820023593)
MFM 10-AF (128311132)

**Software version
number:**

1.590

**Previous version
number:**

1.578

Date of release:

15/03/2018

Release summary:

Bugfix

- Corporate identity design applied
- Default value in dialogue for storage on USB stick now „YES“
- Communication failure during start-up while updating firmware fixed
- Reduction of baud rate during storage process on USB
- Error message when external safety switch is connected fixed

New features

- language packages added (Slovenian)

Files:

MFM10_1590.exe
MFM10_1590.zip

Production site:

Baunach

Product manager:

Dominik Nowak

