

Multifunction tester



- True LoopTM test with patented Confidence MeterTM
- CertSuite Installation compatible Bluetooth® result transfer
- Next generation 2-wire and 3-wire non-trip loop testing
- User upgradeable operating system
- High resolution 0.001Ω loop test
- Automatic volt-drop measurement
- Stabilised insulation test voltage
- Configurable RCD and EV auto-sequence tests
- Fast switch rechargeable plug-in battery pack
- Full colour TFT bonded display
- Re-designed lead set and carry case solution
- IP54 operational housing

DESCRIPTION

The MFT-X1 new electrical installation testing platform MFT-X1 is the first of a new generation of firmware upgradeable, full functionality multi-function testers for low voltage electrical installations.

Intended for use on all low voltage electrical installations including EV charge points and domestic photo-voltaic systems, the range of test capabilities allow for general commissioning of installations and periodic maintenance as well as detailed fault diagnostics.

FEATURES

True Loop™

True Loop™ impedance testing is now a standard feature on the MFT-X1. The latest 3-wire non-trip loop testing technology, incorporated with the patented Confidence Meter™, offers an unmatched, reliable, accurate, stable and repeatable loop test solution to the user, allowing testing in the most hostile high noise conditions or close to the source of supply. The technology also removes the risk of RCD uplift whilst reducing typical test times – even on circuits protected by 10 mA protective devices.

Patented Confidence meter technology

All loop impedance ranges are now supported by the Megger patented Confidence meter technology, reducing typical test times for non-trip loop testing to around 7 seconds on quiet circuits, and providing optimised test times for loop impedance testing in difficult noisy supplies. The Confidence meter shows the progress of the loop measurement and indicates the presence of noise on the circuit, removing erroneous values to give a stable and consistent result.

MFT-X1 result downloading and CertSuite Installation

Test results can be tagged with circuit data and transferred to CertSuite Installation, the latest cloud base electrical certification software package from Megger.

When connected to a mobile device using the low energy Bluetooth® mode, results can be sent directly from the MFT-X1 to an Android or IOS device running Megger CertSuite software. These results are also synchronised with the cloud-based application.

With a wide range of certification options, CertSuite Installation is available as a monthly or yearly subscription package for electrical certification of installations taking results directly from the MFT whilst testing. CertSuite Installation is suitable for multiple concurrent users and is optimised for use with the MFT-X1.



Multifunction tester

Results can be stored and reviewed remotely by users whilst on site from different locations, accessed by head office or other users with the relevant permission, with professional looking certification and reports.

High resolution loop impedance testing

The MFT-X1 has extended the low end of the loop impedance range from 0.01 ohms to 0.001 ohms resolution and 50 kA current calculation. The True Loop impedance measurement using the patented confidence meter makes these low impedance measurements a realistic option, with two wire test connections and high current testing.

RCD custom testing

RCD testing can now be optimised with the RCD test configurator. Select a whole suite of tests or only those elements of the RCD you require. You can even add ramp testing to the sequence, optimising and simplifying testing.

EV Charge point testing

Suitable for both EV charger installation testing with either RCD Type B or RDC protected charge points. The MFT-X1 in conjunction with the Megger EVCA adaptor can test all known EV chargers for installation or maintenance.

Stabilised insulation test voltage

For the first time in any multifunction tester, the MFT-X1 incorporates a stabilised insulation test voltage, ensuring output voltage is accurate to within +/-2% +2 digits. This compares to the industry standard of +20% and so provides a more accurate test voltage without the risk of over-voltage damage to circuits or sensitive components.

Current measurement

The MFT-X1 uses current clamps for current measurement using the optional Megger MCC1010* current clamp for measurement of AC currents from 1 mA to 1000 A.

*Optional accessory

Customer upgradeable operating system

The operating system of the MFT-X1 range is upgradable by the user, simply by downloading the latest operating system file (.BIN) from the Megger web site to a suitable microSD card.

Insert the updated microSD card and pressing TEST initiates an automatic update process without the need for further user intervention.

Display and user interface

The user interface utilises the flexibility of the high contrast 480 x 272 colour, TFT bonded display, with a monochrome black on white mode designed specifically for use in difficult lighting conditions.

Enhancing the colour coded test selection rotary dial, range selection is now replicated on the instrument screen, ensuring easy use in poor lighting environments. Hot keys for second level functions are clearly shown across the top of each screen and the second control dial provides users with a further quick selection option of any highlighted feature, even if wearing protective gloves.

Relevant information is clearly shown on the display, both before and after each test, in full colour, and includes the Confidence MeterTM progress bar, RCD ramp test progress as well as the insulation and continuity measurement bar graph. The new Voltage Widget, displays the L-N, L-E and N-E voltages.

Li-ion or AA Alkaline battery solution

The Megger MFT-X1 is powered by the Megger Li-ion battery pack. The unique 4 Ahr rechargeable Li-ion battery provides the fastest and most flexible battery change solution in the industry. Alternatively an AA Alkaline adaptor is available as an optional accessory.

APPLICATIONS

The primary application is the testing of low voltage electrical installations in domestic, commercial, and industrial installations for single and three phase systems.

The wide range of test capabilities extend the use of the MFT-X1 to include:

- EV charge point testing
- Domestic PV testing
- Motor/Generator testing
- Machine testing
- Portable appliance safety testing
- Panel building and switchgear manufacturing
- Cable testing

Graphical assistance

The instrument has context help to provide graphical circuit connection guidance for each of the measurements.

Accessories

The MFT-X1 is shipped in a rugged, weather-proof carry case offering outstanding protection and flexible storage. Also included is a complete set of test leads to meet the wide range of connection challenges in modern electrical systems.



Multifunction tester

FUNCTIONAL SUMMARY

Voltage measurement		
Voltage range	0.001 V to 2 V (mV range) 2 V to 600 V (V range),	
	1000 V DC (Non-CAT rated circuits)	
Voltage type:	Trms, AC, DC	
Phase sequence	Automatic phase sequence testing on detection of valid three phase supplies	
Current measurement (non-cont	tact)	
AC Trms	Using optional accessories: MCC1010 current clamp	
Measurement Range	MCC1010: 1 mA to 300 A	
Continuity/Resistance		
Measurement range Digital display	$0.01~\Omega$ to 999 k Ω Auto-ranging	
Measurement Range Analogue arc	0 Ω to 1 MΩ log scale	
Test voltage	4 V DC to 5 V DC	
Test current (Nominal)	>200 mA 0Ω >< 2Ω	
	10 mA	
	Auto reduction on high resistance (actual current reported in display)	
Test polarities	Forward polarity	
Buzzer resistance range	$> 0.01 \Omega < 2 k\Omega$	
Buzzer threshold	0.3, 0.5, 1, 2, 3, 4, 5, 10, 20, 30, 40, 50, 100, 200 Ω	
Insulation testing		
Measurement range Digital display	$0.001~\text{M}\Omega$ to $999~\text{M}\Omega$ Auto-ranging	
	0.004 MO to 1.000 MO lon only	
Measurement range Analogue arc	0.001 MΩ to >1000 MΩ log scale	
Insulation test voltages	50 V DC to 1000 V DC + Variable 50 V to 999 V	
Test current	1 mA to 2 mA	
Stabilised output voltage	Output test voltage stabilised to -0% +2% +2 V	
Two Lasa TM lasa impositores target	4t	
True Loop™ loop impedance tes 2 Wire – all modes	sung	
	Mode 1: Non-Trip	
Test types	Mode 2: High current	
	Mode 3: High resolution	
Resolution	Non-Trip: 0.01Ω	
RESOLUTION	High current: 0.01Ω	
	High resolution: 0.001Ω	
Voltage range	Non-trip: 48 V AC to 280 V AC	
voltage range	·	
	High current: 48 V AC to 550V AC High resolution: 48 V AC to 550 V AC	
Eroguanov rango	45 Hz to 65 Hz (all modes)	
Frequency range	43 FIZ (U U3 FIZ (dil HIUUES)	



Multifunction tester

3 Phase testing	Non-trip: Single phase only
	High current: Three phase
	High resolution: Three phase
3 wire - non-trip	
Test types	RCD (non-trip)
	RCD EV (non-trip on 6mA EV RDCs)
Resolution	0.01 Ω
Voltage range	48 V AC to 280 V
Frequency range	45 Hz to 65 Hz
3 Phase testing	Single phase only
Volt drop	
Volt drop calculation	Requires Zref (Ze) and circuit current (I-vdrop)
Accuracy	Dependent on loop impedance accuracy
RCD testing	
RCD types supported	Type AC, A, B, AC(S), A(S), B(S)
Auto RCD sequence	1 / 2x IΔn, 1x IΔn, 2x IΔn, 5x IΔn, Ramp, 0° / 180°
	(customer configurable)
Ramp testing	10 mA to 1000 mA
RDC testing	6 mA RDC
Fault (Touch) voltage	0 V to 253 V
Earth testing	
2 wire	2 wire earth resistance test
3 wire	3 wire earth resistance
3 wire ART	3 wire testing with additional MCC1010 current clamp
Stakeless	Stakeless testing using the MCC1010 and MVC1010 clamps





Multifunction tester

SPECIFICATIONS

Voltage measurement

Function	Range	Accuracy
Voltage DC	0 V - ±1000 V	±1% ± 3 digits
Voltage AC/TRMS	0 V – 600 V (15 – 500 Hz)	±2% ± 1 digits
Frequency	15 Hz – 99 Hz	±0.5% ± 2 digit
	100 Hz – 500 Hz	±2.0% ± 2 digit

Millivolt measurement

Function	Range	Accuracy
mV AC/TRMS	0 mV to 1999 mV (50 / 60 Hz)	$\pm 1\% \pm 3$ digits
mV DC	0 mV to ±1999 mV	$\pm 1\% \pm 3$ digits

Live Earth detection

Indicates if the PE terminal is live when selecting the Loop or RCD test ranges. The relevant Loop or RCD test is inhibited.

Current

Function	Range	Accuracy
Current AC/TRMS	0.001 A - 0.100 A	±2% ±3 digits
	0.100 A – 2.000 A	±2% ±3 digits
	2.00 A – 20.00 A	±2% ±3 digits
	20.0 A – 300.0 A	±2% ±3 digits
Frequency Bandwidth	15 Hz – 50	0 Hz
Influence of Frequency	30 Hz – 500 Hz	≤0.25 %

Resistance and Continuity

Function	Range	Test Current	Accuracy
200 mA	0.01 Ω – 99.9 Ω	$(0 \Omega - 2 \Omega) 205 \text{ mA} \pm 5 \text{ mA}$	±3% ±2 digits
10 mA	0.01 Ω – 99.9 Ω	10 mA	±3% ±2 digits
	100 Ω – 999 kΩ		±5% ±2 digits
Open circuit voltage	4 V to 5 V		

EN61557-4 Measurement Range: 0.10 Ω to 999 $k\Omega$.

Safety and electrical protection

Safety rating:	CAT III 600 V / CAT IV 300 V to EN 61010, IEC 61010-031 : 2015, IEC 61010-030.	Safety category rating valid to altitude of 2000 m.
Live voltage:	J .	n any test terminals without blowing a fuse. Live voltage applied between any test terminals. Fuse protected to



Multifunction tester

Insulation test

Function	Range	Accuracy
1000 V	0.001 – 999 MΩ	±3% ±2 digits
500 V	$0.001 - 500 \text{ M}\Omega$	±3% ±2 digits
500 V	> 500 MΩ	±10%
250 V	0.001 – 250 MΩ	±3% ±2 digits
230 V	> 250 MΩ	±10%
100 V	$0.001-100~\text{M}\Omega$	±3% ±2 digits
100 V	> 100 MΩ	±10%
50 V	$0.001-50~\text{M}\Omega$	±3% ±2 digits
30 V	> 50 MΩ	±10%
VAR	Leakage current > 1 mA	±3% ±2 digits
50 V – 999 V	Leakage current < 1 mA	±10%
Leakage current	0.1 μA – 1.99 mA	±10%
Output voltage	-0% +2% +2 V at rated load or le	SS
Voltage display	±1% ± 3 V	
Short circuit current	1.5 mA nominal	
Test current on load	1 mA at min pass values of insulation	
Maximum capacitance	2 μF for a stable reading, 5 μF absolute limit	

EN61557-2 Measurement Range: 0.10 M Ω to 999 M Ω .

Loop 2-Wire - No RCD (L-PE, L-N or L-L)

Function	Range	Accuracy
2-Wire HR	0.001 – 9.999	±2% ±0.030 Ω
	0.01 Ω – 9.99 Ω	±2% ±5 digits
2-Wire	10.0 Ω – 99.9 Ω	±10% ±5 digits
	100 Ω – 1999 Ω	±10% ±5 digits
Supply Voltage	48 V – 550 V	
Supply Frequency	45 Hz – 65 Hz	

Can be used to measure supply source resistance quickly and reliably between Line and PE or two Live conductors up to 550 V.

EN61557-3 Measurement Range: 0.30 Ω to 1999 Ω

Loop 2-Wire L-PE with RCD

Function	Range	Accuracy
	0.01 Ω – 1999 Ω	±10% ±5 digits
Supply Voltage	48 V – 2	80 V
Supply Frequency	45 Hz – 6	55 Hz

Note: Uses the Megger Confidence Meter to measure the supply source impedance of circuits protected with an RCD rated ≥30 mA when there are only two connections possible. When a neutral is available the three-wire test will provide a quicker, more accurate result.

Note: RCD may trip if there are high leakage currents in the circuit under test. This measurement is immune to the effect of inductance found in some RCDs as it measures resistance (RCD Uplift).

EN61557-3 Measurement Range: 1.00 Ω to 1999 Ω



Multifunction tester

Loop 3-Wire L-PE with RCD

Designation	Test Current	Application
RCD	15 mA	For circuits protected by an RCD rated <= 30 mA
RDC EV	3 mA	For EV charger circuits protected by a RDC and a Type A RCD rated <= 30 mA

Function	Range	Accuracy
	0.01 Ω – 9.99 Ω	±2% ±5 digits
	10.0 Ω – 199 9 Ω	±10% ±5 digits
Supply Voltage	48 V – 280 V	
Supply Frequency	45 Hz – 65 Hz	

Note: Uses the Megger Confidence Meter to measure the supply source impedance of circuits protected with an RCD when three connections are possible. The L-N Loop resistance needs to be less than 12 Ω . The resistances of the L-PE, L-N and N-PE loops are all shown, and the accuracy of the L-PE resistance depends on the maximum resistance displayed. When the neutral is not available the two-wire test must be used.

Note: RCD may trip if there are high leakage currents in the circuit under test. This measurement is immune to the effect of inductance found in some RCDs as it measures resistance.

EN61557-3 Measurement Range: 1.00 Ω to 1999 Ω

RCD Tests Types A and AC

RCD Types	AC, A, AC(S), A(S)	
RCD Rated Current (I∆n)	10 mA, 30 mA, 100 mA, 300 mA,	
	500 mA, 650 mA, 1000 mA, VAR	
1/2 I no-trip Test Current	-10% − +0% 0.5 I∆n	
1 I, 2 I, 5 I trip test – AC current	-0% – +10% M • I∆n	
1 I, 2 I, 5 I trip test – pulsed DC current	-0% - +10% 1.4 • M • I∆n	
Trip time	±10%	
Ramp trip test current	±5%	
Fault Voltage (0 V – supply)	+5% +15% ±0.5 V	
Supply Voltage	48 V – 280 V	
Supply Frequency	45 Hz – 65 Hz	

Type B

RCD Types	B, B(S)
RCD Rated Current (I∆n)	10 mA, 30 mA, 100 mA, 300 mA, 500 mA
1/2 I no-trip Test Current	-10% − +0% (0.5 l∆n)
1 I, 2 I, 5 I trip test Current	-0% − +10% (2 I∆n)
Trip time	±10%
Trip current (ramp)	±5%
Fault Voltage (0 V – supply)	+5% +15% ±0.5 V
Supply Voltage	48 V – 280 V
Supply Frequency	45 Hz – 65 Hz



Multifunction tester

RDC (Type EV) with a 30 mA Type A RCD

Test current	2.0 mA increasing to 6.3 mA before being held at that current for 10s.
Trip time	±1% ±1 ms
Trip current (ramp)	± 5%
Fault Voltage (0 V – supply)	+5% +15% ±0.5 V
Supply Voltage	48 V – 280 V
Supply Frequency	45 Hz – 65 Hz

Earth

Function	Range	Accuracy
2-Wire test	0.01 Ω – 1999 Ω	±2% ±3 digits
Test Frequency	128 Hz	
Test Current	4.5 mA	
Maximum auxiliary electrode resistance (3-wire test)	5 kΩ	

Note: The 2-wire earth test measures resistance between the blue and green terminals using a 128 Hz square wave; the result includes the resistance of test leads.

EN61557-5 Measurement Range: 1 Ω to 1999 Ω .

Function	Range	Accuracy	
3 wire test	0.01 Ω to 1999 Ω	±2% ±3 digits	
Test frequency	128 Hz		
Test current	25 V, 4.5 mA		
Maximum auxiliary electrode resistance	5 kΩ for 25 V		

Function	Range	Accuracy
3P ART	0.01 Ω to 1999 Ω	±5% ±3 digits
Test frequency	128 Hz	
Test current	25 V, 4.5 mA	
Minimum test current through the clamp	5 %	
Maximum auxiliary electrode	$5 \text{ k}\Omega$ for 25V	
resistance	or 100 $k\Omega$ for 50 V	

EN 61557-5 Measurement Range: 1 Ω to 1999 Ω .

Function	Range	Accuracy
Stakeless	1.0 Ω to 60 Ω	±7% ±5 digits
Test frequency	128 Hz	

EN 61557-5 Measurement Range: $1.00~\Omega$ to $40.0~\Omega$.



Multifunction tester

Power supply

Li-ion rechargeable	7.2 V DC 4400 mAh (non-serviceable) + charge status indication
Battery charger (Li-ion)	Input: 110 V / 230 V AC, 50/60Hz, 1.3 A
	Output: 3 A, 8.4 V DC
Battery life (Li-ion)	Li-ion: 4400 mAh = >15 hrs*
	Continuity: Approximately 2000 tests using Li-ion battery
	(0.5s test every 30s per EN 61557)
	Insulation: Approximately 1400 tests using Li-ion battery
	(0.5s test every 30s per EN 61557)
	Earth: Approximately 1600 tests using Li-ion battery
	*times based on typical daily test profile
Battery charging time	Li-ion: 2.5 to 3 hrs (ambient temperature dependent)
LR6 (AA) battery module	8 x LR6 (AA) Alkaline batteries

Environmental

Conditions	Range
Operating Temperature	-10 °C to +55 °C
Storage Temperature	-25 °C to +70 °C
Operating Humidity	90% R.H. at +40 °C max
Ingress Protection	IEC 60529: IP 54: Equipment is protected against ingress of dust and water splashes and is
	suitable for indoor and outdoor use.
Vibration	MIL-PRF-28800F:class 2
Maximum operating altitude	2000 m
Pollution degree	2

Mechanical

Length	274 mm (10.79 ")
Width	96 mm (3.78 ")
Depth	143 mm (5.63 ")
Weight – Instrument only	1.57 kg (3.46 lb)
Shipping weight	5.6 kg (12.35 ib)

Multifunction tester



	ORDERING I	NFORMATION
Description	Part number	Description
MFT-X1-BS Multifunction tester BS1363	1012-223	Optional and repla
MFT-X1-SC Multifunction tester Schuko	1012-225	Multipurpose hard
MFT-X1-CH Multifunction tester Switzerland	1012-229	Blow moulded car
MFT-X1-AU Multifunction tester AUS/NZ	1012-230	Switched test prob
		Neck strap replace
Included accessories		Li-ion battery 440
Switched test probe SP5		SIA10 MAINS sock
Red test lead, probes, clips and grabbers		SIA20 Mains socke
Blue test lead, probe, clips and grabbers		SIA40 Mains sock
Green test lead, probe, clips and grabbers		SIA45 Bipolar Mai
Earth test spike and leads kit		SIA50 Mains socke
Li-ion battery 4400 mAh		SIA60 Mains socke
Li-ion battery charger		Li-ion battery char
SIA10 MAINS socket interface adaptor UK (boxe	ed)	3 lead set RD/GN/
Neck strap		3 lead pro set RD/
Multipurpose hard base carry case		3 lead set RD/GN/
Quick start guide		3 piece grabber se
Calibration certificate		7 piece probe and
		3 lead RD/GN/BU

Multipurpose hard base carry case 1014-985 Blow moulded carry case (Polypropylene) 1013-453 Switched test probe SP5 1002-774 Neck strap replacement 1013-454 Li-ion battery 4400 mAh 1013-450 SIA10 MAINS socket interface adaptor UK (boxed) 1014-300 SIA20 Mains socket interface adaptor AU 1007-170 SIA40 Mains socket interface adaptor SCHUKO 1007-171 SIA45 Bipolar Mains socket interface adaptor SCHUKO 1007-171 SIA50 Mains socket interface adaptor CH 1007-164 SIA50 Mains socket interface adaptor USA 1007-087 Li-ion battery charger 1013-451 3 lead set RD/GN/BU non-fused (boxed) 1014-291 3 lead set RD/GN/BU non-fused (boxed) 1014-292 3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 1014-299 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) 1014-301 Bearth test spike and leads kit 1001-810 MCC 1010 Current clamp 1010-516 MVC1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-838 LA-KIT Lamp adaptor kit 1013-452 UKAS Calibration certificate 1013-460	Description	Part number
Blow moulded carry case (Polypropylene) Switched test probe SP5 1002-774 Neck strap replacement 1013-454 Li-ion battery 4400 mAh 1013-450 SIA10 MAINS socket interface adaptor UK (boxed) 1014-300 SIA20 Mains socket interface adaptor AU 1007-170 SIA40 Mains socket interface adaptor SCHUKO 1007-171 SIA45 Bipolar Mains socket interface adaptor SCHUKO 1007-178 SIA50 Mains socket interface adaptor CH 1007-164 SIA60 Mains socket interface adaptor USA Li-ion battery charger 1013-451 3 lead set RD/GN/BU non-fused (boxed) 3 lead pro set RD/GN/BU non-fused (boxed) 1014-291 3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 1014-299 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) - fused leads only MCC1010 Current clamp 1010-516 MVC 1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-838 LA-KIT Lamp adaptor kit 1013-452	Optional and replacement accessories	
Switched test probe SP5 Neck strap replacement Li-ion battery 4400 mAh SIA10 MAINS socket interface adaptor UK (boxed) SIA20 Mains socket interface adaptor AU SIA40 Mains socket interface adaptor SCHUKO SIA45 Bipolar Mains socket interface adaptor SCHUKO SIA50 Mains socket interface adaptor CH SIA60 Mains socket interface adaptor USA Li-ion battery charger Li-ion battery charger 3 lead set RD/GN/BU non-fused (boxed) 3 lead pro set RD/GN/BU non-fused (boxed) 3 piece grabber set RD/GN/BU fused 10 A (boxed) 7 piece probe and clip set RD/GN/BU (boxed) 3 lead RD/GN/BU fused 10 A (boxed) 1014-299 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) 1014-301 MCC1010 Current clamp 1010-516 MVC 1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-838 LA-KIT Lamp adaptor kit 1013-452	Multipurpose hard base carry case	1014-985
Neck strap replacement Li-ion battery 4400 mAh Li-ion battery 4400 mAh SIA10 MAINS socket interface adaptor UK (boxed) SIA20 Mains socket interface adaptor AU D07-170 SIA40 Mains socket interface adaptor SCHUKO D07-171 SIA45 Bipolar Mains socket interface adaptor SCHUKO D07-158 SIA50 Mains socket interface adaptor CH D07-164 SIA60 Mains socket interface adaptor USA Li-ion battery charger D1013-451 Blead set RD/GN/BU non-fused (boxed) D14-291 Blead pro set RD/GN/BU non-fused (boxed) D14-292 Blead set RD/GN/BU fused 10 A (boxed) D14-295 Bpiece grabber set RD/GN/BU (boxed) D14-299 Ppiece probe and clip set RD/GN/BU (boxed) D14-301 Blead RD/GN/BU fused 10 A (boxed) D14-301 Blead RD/GN/BU fused 10 A (boxed) D14-304 Earth test spike and leads kit D01-810 MCC1010 Current clamp MVC1010 Voltage clamp D1010-518 MSA1363 socket adaptor UK D13-838 LA-KIT Lamp adaptor kit D1013-452	Blow moulded carry case (Polypropylene)	1013-453
Li-ion battery 4400 mAh SIA10 MAINS socket interface adaptor UK (boxed) SIA20 Mains socket interface adaptor AU SIA40 Mains socket interface adaptor SCHUKO SIA45 Bipolar Mains socket interface adaptor SCHUKO SIA50 Mains socket interface adaptor SCHUKO SIA60 Mains socket interface adaptor USA SIA60 Mains socket interface adaptor USA Li-ion battery charger 1013-451 3 lead set RD/GN/BU non-fused (boxed) 1014-291 3 lead pro set RD/GN/BU non-fused (boxed) 1014-292 3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 1014-299 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) – fused leads only MCC1010 Current clamp 1010-516 MVC1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-452	Switched test probe SP5	1002-774
SIA10 MAINS socket interface adaptor UK (boxed) SIA20 Mains socket interface adaptor AU SIA40 Mains socket interface adaptor SCHUKO SIA45 Bipolar Mains socket interface adaptor SCHUKO SIA50 Mains socket interface adaptor CH SIA60 Mains socket interface adaptor USA SIA60 Mains socket interface adaptor USA Li-ion battery charger 1013-451 3 lead set RD/GN/BU non-fused (boxed) 3 lead pro set RD/GN/BU non-fused (boxed) 1014-291 3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 1014-299 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) - fused leads only MCC1010 Current clamp 1010-516 MVC1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1013-452	Neck strap replacement	1013-454
SIA20 Mains socket interface adaptor AU SIA40 Mains socket interface adaptor SCHUKO SIA45 Bipolar Mains socket interface adaptor SCHUKO SIA50 Mains socket interface adaptor CH SIA60 Mains socket interface adaptor USA Li-ion battery charger 1013-451 3 lead set RD/GN/BU non-fused (boxed) 1014-291 3 lead pro set RD/GN/BU non-fused (boxed) 1014-292 3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) 1014-301 MCC1010 Current clamp MCC1010 Current clamp MCC1010 Voltage clamp 1010-516 MVC 1010 Voltage clamp MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1013-452	Li-ion battery 4400 mAh	1013-450
SIA40 Mains socket interface adaptor SCHUKO SIA45 Bipolar Mains socket interface adaptor SCHUKO SIA50 Mains socket interface adaptor CH SIA60 Mains socket interface adaptor USA Li-ion battery charger 1013-451 3 lead set RD/GN/BU non-fused (boxed) 1014-291 3 lead pro set RD/GN/BU non-fused (boxed) 1014-292 3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) 1014-301 MCC1010 Current clamp MVC1010 Voltage clamp 1010-516 MVC1010 Voltage clamp MSA1363 socket adaptor UK MTF230 – Schuko (Type-F) Socket adaptor LA-KIT Lamp adaptor kit 1013-452	SIA10 MAINS socket interface adaptor UK (boxed)	1014-300
SIA45 Bipolar Mains socket interface adaptor SCHUKO SIA50 Mains socket interface adaptor CH SIA60 Mains socket interface adaptor USA Li-ion battery charger 1013-451 3 lead set RD/GN/BU non-fused (boxed) 1014-291 3 lead pro set RD/GN/BU non-fused (boxed) 1014-292 3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 1014-299 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) 1014-301 MCC1010 Current clamp 1010-516 MVC1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1007-158 1007-087 1007-087 1007-087 1014-291 1014-291 1014-292	SIA20 Mains socket interface adaptor AU	1007-170
SIA50 Mains socket interface adaptor CH SIA60 Mains socket interface adaptor USA Li-ion battery charger 1013-451 3 lead set RD/GN/BU non-fused (boxed) 1014-291 3 lead pro set RD/GN/BU non-fused (boxed) 1014-292 3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) 1014-301 4 lead RD/GN/BU fused 10 A (boxed) 1014-301 MCC 1010 Current clamp 1010-516 MVC 1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1013-452	SIA40 Mains socket interface adaptor SCHUKO	1007-171
SIA60 Mains socket interface adaptor USA 1007-087 Li-ion battery charger 1013-451 3 lead set RD/GN/BU non-fused (boxed) 1014-291 3 lead pro set RD/GN/BU non-fused (boxed) 1014-292 3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 1014-299 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) – fused leads only 1014-304 Earth test spike and leads kit 1001-810 MCC 1010 Current clamp 1010-516 MVC 1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	SIA45 Bipolar Mains socket interface adaptor SCHUH	(O 1007-158
Li-ion battery charger 1013-451 3 lead set RD/GN/BU non-fused (boxed) 1014-291 3 lead pro set RD/GN/BU non-fused (boxed) 1014-292 3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 1014-299 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) – fused leads only 1014-304 Earth test spike and leads kit 1001-810 MCC1010 Current clamp 1010-516 MVC1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	SIA50 Mains socket interface adaptor CH	1007-164
3 lead set RD/GN/BU non-fused (boxed) 1014-291 3 lead pro set RD/GN/BU non-fused (boxed) 1014-292 3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 1014-299 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) – fused leads only 1014-304 Earth test spike and leads kit 1001-810 MCC 1010 Current clamp 1010-516 MVC 1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	SIA60 Mains socket interface adaptor USA	1007-087
3 lead pro set RD/GN/BU non-fused (boxed) 1014-292 3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 1014-299 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) – fused leads only 1014-304 Earth test spike and leads kit 1001-810 MCC 1010 Current clamp 1010-516 MVC 1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	Li-ion battery charger	1013-451
3 lead set RD/GN/BU fused 10 A (boxed) 1014-295 3 piece grabber set RD/GN/BU (boxed) 1014-299 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) – fused leads only 1014-304 Earth test spike and leads kit 1001-810 MCC1010 Current clamp 1010-516 MVC1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	3 lead set RD/GN/BU non-fused (boxed)	1014-291
3 piece grabber set RD/GN/BU (boxed) 1014-299 7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) – fused leads only 1014-304 Earth test spike and leads kit 1001-810 MCC1010 Current clamp 1010-516 MVC1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	3 lead pro set RD/GN/BU non-fused (boxed)	1014-292
7 piece probe and clip set RD/GN/BU (boxed) 1014-301 3 lead RD/GN/BU fused 10 A (boxed) – fused leads only 1014-304 Earth test spike and leads kit 1001-810 MCC1010 Current clamp 1010-516 MVC1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	3 lead set RD/GN/BU fused 10 A (boxed)	1014-295
3 lead RD/GN/BU fused 10 A (boxed) – fused leads only 1014-304 Earth test spike and leads kit 1001-810 MCC1010 Current clamp 1010-516 MVC1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	3 piece grabber set RD/GN/BU (boxed)	1014-299
Earth test spike and leads kit 1001-810 MCC1010 Current clamp 1010-516 MVC1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	7 piece probe and clip set RD/GN/BU (boxed)	1014-301
MCC1010 Current clamp 1010-516 MVC1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	3 lead RD/GN/BU fused 10 A (boxed) – fused leads of	only 1014-304
MVC 1010 Voltage clamp 1010-518 MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	Earth test spike and leads kit	1001-810
MSA1363 socket adaptor UK 1013-837 MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	MCC1010 Current clamp	1010-516
MTF230 – Schuko (Type-F) Socket adaptor 1013-838 LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	MVC1010 Voltage clamp	1010-518
LA-KIT Lamp adaptor kit 1014-833 AA battery module 1013-452	MSA1363 socket adaptor UK	1013-837
AA battery module 1013-452	MTF230 – Schuko (Type-F) Socket adaptor	1013-838
	LA-KIT Lamp adaptor kit	1014-833
UKAS Calibration certificate 1013-460	AA battery module	1013-452
	UKAS Calibration certificate	1013-460



